

GENERAL ELECTRIC COMPANY, CORPORATIONS PARK, BUILDING 702, SCHENECTADY, NEW YORK 12345, Phone (518) 374-2211

OUTDOOR

POWER EQUIPMENT

OPERATION

March 5, 1974

TO: ELEC-TRAK TRACTOR DEALERS

SUBJECT: ER8-36 RIDER

When raising and lowering the fully assembled mower deck with the lift handle, the added weight on the mowers right side from the added safety chute and mower extension causes it to lift unevenly. To better balance the mower for these lifts, we suggest you remove the mower lift assist spring on the left side. The top end of the spring is located underneath the seat and to its left, and the other end on the mower deck left side.

Sincerely,

J. W. Stackhouse, Manager - Product Planning

JWS/1ba

CC: Outdoor Power Equipment Operation Salesmen

