

## PRODUCT SERVICE BULLETIN NO. 72-27 (27)

## 38" Snow Thrower Shipments

Some early reports indicate that the AD38 Snow Thrower can suffer concealed damage if mishandled during shipping. Since the shipping container does not always show evidence of mishandling, it is suggested that inspection of these snow throwers be made at the time of delivery and if any damage is found, this should be noted on the bill of lading that you sign. Then take the proper steps to make your claim as outlined in your Dealer Franchise Manual. In particular, check the area of the auger housing near the drive motor for dents or paint damage.

## 38" Snow Thrower Set-Up

During initial set-up of any 38" Snow Throwers, alignment of the drive belt should be checked and adjusted, if necessary, to run true. Proper alignment will reduce vibration, noise, and belt wear.

## **Price Correction**

Please correct the prices in the parts manual as follows:

Wiring Harness 247A7351G1  $\frac{\text{Dlr Net}}{2.75}$   $\frac{\text{Sug List}}{3.65}$